


Uniloy Impact Trimmer Automatic Platen Drive Chain Tensioner

Uniloy is proud to introduce the automatic platen drive chain tensioner. This assembly cushions the operation of the platen drive chain while eliminating slack. It is suitable for all 10039, 10040, 10041 or 10042 impact trimmers using double 50 or double 60 chain.



Benefits

- Smoother platen drive operation
- Eliminates slack due to chain stretch
- Reed switches and indicator lights indicate when maintenance is required
- Reduces wear and tear on drive components
- Reduces down time and maintenance costs

Machine Requirements

- 10039, 10040, 10041, or 10042 trimmer
- Double 50 or 60 chain

Features

To Include:

- Tensioner cylinder
- Mounting bracket
- Pivot bracket
- Clevis bracket
- Tensioner sprocket
- Two reed switches
- Indicator lights
- Electrical wire and fittings
- Partially assembled prior to shipment

For more information including pricing for this or any other machine upgrade, please contact your local Uniloy Sales Representative. Trained Uniloy Service Technicians are available to assist in the installation of these packages at your facility. All Uniloy retrofit packages are engineered to suit your individual machine specifications.